

Golf Course Maintenance Building No. 1

Herrick Archives Building 175

A. IDENTIFICATION & LOCATION

1. Name

1.1 Never officially named by Board of Trustees action.


1.2 Alternate names noted:

Storage Building, University Golf Course
Maintenance Building, University Golf Course
Service Building

2. Location

2.1 Located at 1471 McCoy Road. See map below. (Originally 1470 McCoy Road. Corrected May 19, 1969).

2.2 For greater detail, see Sheet GC 6 and 7 in the book of campus maps in the University Archives.



For identification of other buildings shown, see Appendix A.

3. General Description

3.1 Type of construction:

Metal frame and skin.

3.2 No. of stories:

One.

3.3 Increments of construction:

No additions.

3.4 Present area of building as shown in inventory records of Office of Campus Planning:

5152 sq. ft. gross; 4600 sq. ft. net assignable.

See Addendum No. 1

3.5 Volume of building:

83,325 cu. ft. (PP)

B. PLANNING & CONSTRUCTION

1. On September 7, 1959 the Board. of Trustees approved the plans and related documents prepared by W. E. Linch and authorized the solicitation of bids by contractors.
2. Bids were received on November 5, 1959 (T). The plumbing bids were rejected and new bids were received on January 29, 1960 (T).
3. On February 12, 1960 the Board of Trustees approved the award by the Vice President of contracts to the following contractors:

General: Ruscilli Construction Company
Electrical: Westgate Electric Company
Plumbing: J. A. Guy
Storm drainage: J. A. Guy

4. Completion and occupancy:

Completed April 15, 1960 (A).

C. PHOTOGRAPHS

1. In Photoarchives:

X7375
X7376

John H. Herrick
November 19, 1975

ADDENDUM NO. 1

Campus Planning records now show the net assignable area of this building as 4,900 square feet.

John H. Herrick
November 8, 1984